



Contact Pop (941) 257-0111

2009 Malibu 216 VLX

Stock # 7289

\$70,500

\$74,000

Year 2009 Type Power Brand Malibu

Category Ski/Wakeboard Boats

Model 216 VLX Length (LOA) 21' 0" Hours 19

Location Reno, Nevada

Storage Status Not currently in storage

Super Low hours!!

This Is a barely broke in Malibu!!! All Fresh water! If you want to be seen on the water. This will do it!!

Here is a list of options and features

The boat has 19.7 hours, has an Indmar lcr 350, has the diamond hull, 3 yr transferable factory warranty,6.5" lcd display called the maliview, front center two rear ballast tanks, transom remote for the stereo, precision pro cruise control, power wedge.

upgraded add ons

Wetsounds ws420 eq with microphone, Wetsounds Rev10 tower speakers power by an alpine pdx-f6, 8 in cabin speakers powered by an alpine pdx-f6, 2 12 solo baric sub woofers p...

Read the entire description on the website by scanning the QR code below.







Contact Pop (941) 257-0111

2009 Malibu 216 VLX

Stock # 7289

Details and Specifications

Engine & M	echanical				
# of Engines	1	Engine Year	2009	Engine Brand	Indmar
Engine Model	ICR	Engine Hours	19	Engine Type	350
Engine Size	350 hp	Fuel Type	Gasoline	Configuration	Inboard/Outboard

es es	Trailer Year	2009	Trailer Brand	Extreme
:	# Brakes	2	Breakaway Hitch	No
				# Brakes 2 Breakaway

Accommodations & P	assengers		
Has Generator No	Has Air Conditioning	No	







Contact Pop (941) 257-0111

2009 Malibu 216 VLX

Stock # 7289

Constructio	n Features		
Hull Material	Fiberglass		

Features

Accommodations

Drink Holders

Deck Gear

- Beverage Holders Bimini

- Cockpit Cover
- Courtesy Lights

Electrical Systems


Battery

Stereo

- Engine Kill Switch
 - Gauges
- Horn







2009 Malibu 216 VLX

Stock # 7289

Mechanical Systems

- 10 Year Hull Warranty
- Bilge Blower
- Steering: Hydraulic
- Starting Type: Electric

Navigational Equipment

- CD Player
- Sound System
- Speed Instrument

Safety Equipment

• Bilge Pump







Contact Pop (941) 257-0111

2009 Malibu 216 VLX

Stock # 7289















Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

